



20421 Bohemian Hall Road, Silverhill AL 36576 | 251-947-4848 | [www.paengines.com](http://www.paengines.com)  
FAA Part 145 Repair Station Number: 8PCR980B

## **PAE ENGINE WARRANTY: 3 YEARS, UNLIMITED HOURS TO TBO**

THIS WARRANTY IS NULL AND VOID IF THE ENGINE IS RUN ON AUTOMOTIVE FUEL.

Pinnacle Aircraft Engines, LLC (PAE) warrants each PAE overhauled Lycoming and Continental certified piston aircraft engine to be free from defects in materials and workmanship for a period of three (3) years or until the expiration of the Original Equipment Manufacturer's (OEM) Time Between Overhaul (TBO) in effect at time of overhaul by PAE, whichever occurs first. This is a limited warranty that covers parts and labor costs and is subject to the terms, conditions, exclusions, and limitations as set forth herein.

Each Pinnacle Aircraft Engines, LLC (PAE) overhauled engine is warranted as follows:

1. (a) For a period of thirty six (36) months or until the expiration of the OEM recommended Time Between Overhaul (TBO), whichever occurs first, after the warranty activation date PAE will, except as excluded below, at its option repair or replace on an exchange basis any engine, component or part overhauled or supplied by it which within the applicable thirty six (36) month or TBO period is returned to PAE and which upon examination is found to the satisfaction of PAE to be defective in workmanship. The warranty activation date is the date the engine is first operated for any use or the (60) days after PAE's invoice date, whichever occurs first.

(b) PAE will pay for reasonable labor costs associated with repairs or replacements under paragraph 1(a) of this policy. The amount of repair and replacement labor costs allowed will be in accordance with the latest revision of the warranty labor allowance schedule, published by PAE. The amount of "troubleshooting" costs allowed will be the reasonable costs under the circumstances of identifying the need for such repairs or replacements, but in no event will the "troubleshooting" costs allowed exceed fifteen percent (15%) of the labor costs associated with such repairs or replacements allowed by PAE. No "troubleshooting" cost allowance will be made where the need for repairs or replacements is identified in the course of overhaul, routine maintenance or on the basis of an obvious defect.

(c) PAE will pay transportation costs in connection with the repair or replacement of any engine, component or part found to the satisfaction of PAE to be defective in workmanship under paragraph 1(a) of this warranty. The engine, component or part must be shipped prepaid to PAE. Transportation cost reimbursement for engines will be the actual surface freight charge or \$500.00, whichever is less. Transportation cost reimbursement for components or parts will be the actual surface freight charge for shipment of the component or part or the currently published UPS surface rate schedule, whichever is less.



2. Repair or replacement of any engine or part under this warranty will not extend the period of warranty coverage set forth above.

5. This warranty applies only to engines in which parts overhauled or supplied by PAE been used and nothing contained herein should be construed as a warranty by PAE of any engine or part not overhauled or supplied by PAE. PAE accepts no responsibility for the failure of any engine or part which it does not overhaul or supply or damage resulting from such failure.

6. This warranty does not apply to any engine, component or part overhauled or supplied by PAE which has been subject to misuse, neglect or accident; has been installed, repaired, maintained or altered in any way that in the judgment of PAE has adversely affected the condition of the engine; or has been operated inconsistent with the original engine and aircraft manufacturers recommendations and limitations.

7. PAE will not be responsible for repair or replacement of any engine, component or part damaged or worn as a result of corrosion, pre-ignition/detonation, operation with non-calibrated engine gauges, improper fuel system adjustment, non-OEM approved fuel, oil, additives or installation of parts, components or accessories that alter the engine's original FAA approved type design.

8. The provisions of this warranty do not apply to normal maintenance service items (such as periodic engine adjustments, inspections, engine or component overhaul resulting from time between overhaul (TBO) recommendations, etc.) or to the replacement of normal service items (such as spark plugs, filters, hoses, belts, etc.).

9. This warranty is a warranty to repair or replace and a not a warranty of the condition or future performance of the products it covers. There are no other warranties, expressed or implied, specifically, but without limitation, there are no implied warranties of the merchantability of fitness for a particular purpose. In no event will PAE be responsible for any incidental or consequential damages arising out of any defect in any engine or part, arising out of the failure of any engine or part to operate properly, or arising out of any breach of the warranty made herein. No person is authorized to give any other warranty or to assume any additional obligation or liability on behalf of PAE.



June 2019

